

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1327
ENE
> 1
1.691 mi.
8931 ft.

BASEMENT
2965 OCEAN AVE
BROOKLYN, NY

NY Spills **S108763843**
N/A

Relative:
Higher

Actual:
10 ft.

SPILLS:

Name: BASEMENT
Address: 2965 OCEAN AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0705729 / 2007-08-22
Facility ID: 0705729
Facility Type: ER
DER Facility ID: 335488
Site ID: 386095
DEC Region: 2
Spill Cause: Human Error
Spill Class: C4
SWIS: 2401
Spill Date: 2007-08-18
Investigator: hrpatel
Referred To: Not reported
Reported to Dept: 2007-08-18
CID: 76
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-08-18
Spill Record Last Update: 2007-08-22
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: FF MACINTYER
DEC Memo: "08/20/07-Hiralkumar Patel. visited site on 08/18/07. met Mr. Sriedman, owner's representative and FDNY. as per FDNY, owner was cutting tank and during that time, fire occurred. found 3000 gal tank sitting on floor. found water inside tank and inside basement. no odors inside basement. use stick to check contents inside tank. found muddy water, but no oil. no oil observed on water on basement floor also. no sign of oil spill (stain or rainbow colors on water). as per Mr. Sriedman, tank was out-of-service for about 6 years. site using gas heating system. FDNY was called because of fire that occurred while cutting tank. found that tank was not gas free before cutting it. looks like un-licensed person was working on tank. FDNY didn't issue any violation for such work. Marlon Sriedman Ph. (718) 916-5042 08/22/07-Hiralkumar Patel. spoke with Mr. Sriedman. they have pumped out muddy water from tank and basement. asked him to register existing tank before doing any more work on tank. he will register tank and will consult PBS unit in DEC prior to any more work on tank removal. in absence of any odor or sign of oil spill, case closed."
Remarks: "caller reports workers removing fuel tank when spill occurred. spill is a mixture of oil and water. dep#1708031."

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

All Materials:

Site ID:	386095
Operable Unit ID:	1143344
Operable Unit:	01
Material ID:	2133621
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported